

DCL L416

Turning the System On

- Press the **[On]** button, on the control panel, once.
- The buttons will flash for approximately 30 seconds as the projector starts up. You may now select a source.

Note: The system must be turned on before sources can be selected.

Using a Laptop

- Connect your laptop to either the end of the VGA or HDMI cable that is not connected to the input panel.
- Select either the **[HDMI]** or **[VGA]** button on the control panel corresponding to the cable used to connect the laptop.

Note: Depending on your laptop model, you may need an adapter. Adapters can be borrowed on short term loan (4hrs.) from an Engineering IT Help Desk.

Using the Resident PC

- Make sure that the PC is turned on and running
- Select the **[PC]** button on the control panel.

Turning the System Off

- Press the **[Off]** button on the control panel
- The buttons will flash for 30-90 seconds as the system shuts down.